

FAT Wrench AutoTorque Battery

[Gun Cleaning & Chemicals](#) > [Brushes & Bore Snakes](#) > [Bore Snakes](#)

Keep your F.A.T. Wrench AutoTorque running with the AutoTorque Spare Battery Pack. This 12V Lithium-Ion battery delivers up to 2 hours of continuous runtime on a single charge, ensuring you're always ready to work.

Easily monitor your power level with the quick-check LED battery status indicator. When it's time to recharge, simply use a USB-C cable (not included) for fast and convenient charging.

⚠️ Compatible only with the F.A.T. Wrench AutoTorque.

NO IMAGE
AVAILABLE

Attributes

- Name: [FAT Wrench AutoTorque Battery](#)
- Manufacturer: [WHEELER](#)
- Product no.: EU2014072
- Mfr. No.: 1223619
- Colour: Black
- Shipping height: 354mm
- Shipping width: 222mm
- Shipping length: 212mm
- UPC: 198700000847

Table of Contents

- Startpage
- FAT Wrench AutoTorque Battery Safety Instructions
- About Us

FAT Wrench AutoTorque Battery Safety Instructions

Introduction

Thank you for choosing the FAT Wrench AutoTorque Battery. This guide provides essential safety instructions to ensure the safe use and maintenance of your battery. Please read this manual carefully before use.

General Safety Guidelines

- Always use the FAT Wrench AutoTorque Battery as intended.
- Ensure that the battery is compatible only with the FAT Wrench AutoTorque.
- Keep the battery away from water and moisture to prevent damage and hazards.
- Do not expose the battery to extreme temperatures or direct sunlight.
- Store the battery in a cool, dry place when not in use.
- Regularly check the battery for any signs of damage or wear.

Specific Safety Precautions for Use

- Avoid shortcircuiting the battery terminals.
- Do not attempt to disassemble or modify the battery.
- Use only a USB-C cable for charging (not included).
- Do not use the battery if it is swollen, leaking, or damaged.
- Keep the battery out of reach of children and pets.
- If the battery is accidentally ingested, seek medical help immediately.

Instructions for Installation and Usage

1. Installation:

- Ensure the FAT Wrench AutoTorque is turned off.
- Locate the battery compartment on the device.
- Insert the FAT Wrench AutoTorque Battery into the compartment, ensuring correct polarity (+/-).
- Close the battery compartment securely.

2. Usage:

- Turn on the FAT Wrench AutoTorque to begin using it.
- Monitor the battery level using the quickcheck LED battery status indicator.
- When the battery is low, connect the USB-C cable to the battery for charging.
- Allow the battery to charge fully before using the device again.

3. Charging:

- Only use a compatible USB-C charger for charging the battery.
- Do not leave the battery charging unattended for extended periods.
- Disconnect the charger once the battery is fully charged.

Disposal Instructions

- Dispose of the battery in accordance with local regulations.
- Do not dispose of the battery in regular household waste.
- Take the battery to a designated recycling facility or collection point for safe disposal.

Contact Information for Further Support

For any safety inquiries or support regarding the FAT Wrench AutoTorque Battery, please contact the manufacturer directly or refer to the product's official website for assistance.

Thank you for your attention to these safety instructions. Your safety is our priority.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk