

RELOADING DIE - RCBS COWBOY SHOTSHELL RELOADING DIE SET 12GA

[Reloading](#) > [Reloading Presses](#) > [Shotshell Presses](#)

The die hard Cowboy Action Shooter not only uses authentic firearms and loads with black powder, but also dresses the part. Many would like to use period correct all brass shotshell ammunition, but with no good way to reload them, colorful plastic hulls continue to be used. Today's modern shotshell presses can handle the powder drop, wad seating and shot drops but could do nothing to handle the sizing, de-priming, re-priming and crimp of a brass case. The RCBS Cowboy Shotshell die answers this need. Designed to be used in any RCBS single stage press with a removable die bushing, it performs just like a rifle sizing die. The Cowboy Shotshell Die will first size and de-prime the case; Re-priming is done with the standard priming provided with the press. Use your shotshell press to fill the case with powder, seat the wad and spacers and dispense your shot charge. Remove the sizing ring and install the finish crimp. Place your over shot card onto the shot charge and run up in to the die to roll crimp the case mouth. A newly handloaded brass shotshell is completed.



Attributes

- Name: [RCBS COWBOY SHOTSHELL RELOADING DIE SET 12GA](#)
- Manufacturer: [RCBS](#)
- Product no.: 000003820
- Mfr. No.: 99060
- Gauge: 12 Gauge
- Delivery weight: 0.544kg
- Shipping height: 25mm
- Shipping width: 114mm
- Shipping length: 152mm
- UPC: 076683990600

Item details

Made in USA

Table of Contents

- [Startpage](#)
- [Safety Instructions for RCBS Cowboy Shotgun Reloading Die Set 12GA](#)
- [About Us](#)

Safety Instructions for RCBS Cowboy Shotshell Reloading Die Set 12GA

Introduction

Thank you for choosing the RCBS Cowboy Shotshell Reloading Die Set 12GA. This product is designed to assist you in safely and effectively reloading brass shotshells for Cowboy Action Shooting. It is important to follow all safety guidelines to ensure a safe reloading experience.

General Safety Guidelines

- Ensure you have read and understood all safety instructions before using the reloading die set.
- Always wear appropriate safety gear, including safety glasses and hearing protection, when reloading.
- Keep the reloading area clean and free of clutter to prevent accidents.
- Store all reloading components, including powders and primers, in a secure and dry location away from children and pets.
- Always check for any signs of damage or wear on your reloading equipment before use.
- Be aware of your surroundings and ensure that no unauthorized persons are present in the reloading area.

Specific Safety Precautions for Use

- Only use the RCBS Cowboy Shotshell Die Set with an appropriate RCBS single stage press that has a removable die bushing.
- Follow the manufacturer's instructions for your specific press model to ensure compatibility and safety.
- Do not exceed the recommended load data for the shotshells you are reloading.
- Ensure that your workspace is wellventilated, especially when handling powders and primers.
- Avoid using any damaged or malfunctioning equipment. If you notice any issues, stop using the equipment immediately and consult the manufacturer.
- Be cautious when handling primers and powders, as they can be sensitive to heat, shock, and friction.

Instructions for Installation and Usage

1. Setup:

- Ensure your RCBS single stage press is securely mounted and stable.
- Remove the die bushing from the press and install the RCBS Cowboy Shotshell Die according to the press manufacturer's instructions.

2. Reloading Process:

- **Sizing and Depriming:**
 - Insert the brass shotshell case into the die and operate the press to size and deprime the case.
- **Repriming:**
 - Use the standard priming tool provided with your press to reprime the sized case.
- **Filling the Case:**
 - Use your shotshell press to fill the case with the appropriate powder charge.
- **Wad Seating:**
 - Seat the wad and any spacers as per your load specifications.
- **Shot Charge:**
 - Dispense the shot charge into the case.
- **Finishing the Crimp:**

- Remove the sizing ring and install the finish crimp die.
- Place your overshot card onto the shot charge and run the case into the die to roll crimp the case mouth.

3. **Final Inspection:**

- Inspect the completed shotshell for any defects or irregularities before use.

Disposal Instructions

- Dispose of all used components, such as spent primers and cases, in accordance with local regulations.
- Do not dispose of hazardous materials, such as powders or primers, in regular trash. Contact local waste management authorities for proper disposal methods.

Contact Information for Further Support

For any questions regarding safety, usage, or troubleshooting, please refer to the manufacturer's website or customer support resources. Ensure you have your product model and any relevant information available when seeking assistance.

By following these safety instructions, you can help ensure a safe and enjoyable reloading experience with your RCBS Cowboy Shotshell Reloading Die Set 12GA. Always prioritize safety and compliance with local regulations when reloading ammunition.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk