

UNIFLOW POWDER MEASURE ACCESSORIES - RCBS UNIFLOW POWDER MEASURE DROP TUBE 17 TO 20 CAL

[Reloading](#) > [Powder Handling](#) > [Measure Stands & Accessories](#)

The RCBS Uniflow Powder Measure will throw consistently accurate charges by volume with all types of smokeless powder. The straight forward measuring cylinder design helps eliminate powder hang ups which can lead to double charges or overcharges. The numbered measuring screw changes easily from charge to charge, and enables you to go back to a known charge at a later date. The precision ground cylinder is honed main casting produce a smooth and accurate powder dispensing system. Mount is a standard 7/8 to fourteen thread, comes with a bench or shelf bracket and two drop tubes for 22 caliber and up. Mounts on the RCBS Powder Measure or the Sinclair Powder Measure Stand (11-1200), accepts Sinclair Drop Tubes with a Sinclair Adapter. DO NOT USE WITH BLACK POWDER.



Attributes

- Name: [RCBS UNIFLOW POWDER MEASURE DROP TUBE 17 TO 20 CAL](#)
- Manufacturer: [RCBS](#)
- Product no.: 100010301
- Mfr. No.: 9028
- Delivery weight: 0.005kg
- Shipping height: 1mm
- Shipping width: 51mm
- Shipping length: 152mm
- UPC: 076683090287

Item details

Made in USA

Table of Contents

- Startpage
- Safety Instruction Guide for RCBS Uniflow Powder Measure Accessories
- About Us

Safety Instruction Guide for RCBS Uniflow Powder Measure Accessories

Introduction

Thank you for choosing the RCBS Uniflow Powder Measure Drop Tube for your reloading needs. This guide provides essential safety instructions and operational guidelines to ensure the safe and effective use of your product. Please read this document carefully before using the product.

General Safety Guidelines

To ensure your safety and the safety of others, please adhere to the following guidelines:

- Always read and understand the product manual before use.
- Use the product only for its intended purpose.
- Keep the product out of reach of children and vulnerable individuals.
- Regularly inspect the product for any signs of wear or damage.
- Do not modify the product in any way.
- Follow all local regulations regarding the use and storage of smokeless powder.
- Report any unsafe conditions or accidents to the appropriate authorities.

Specific Safety Precautions for Use

When using the RCBS Uniflow Powder Measure Drop Tube, observe the following precautions:

- DO NOT USE WITH BLACK POWDER. This product is designed specifically for smokeless powder.
- Ensure the measuring screw is securely adjusted before use to avoid accidental overcharges.
- Avoid overfilling the powder measure to prevent spills and potential hazards.
- Use in a wellventilated area to minimize exposure to powder dust.
- Always wear protective eyewear when operating the powder measure.
- Keep the work area clean and free from clutter to reduce the risk of accidents.

Instructions for Installation and Usage

Follow these steps for proper installation and usage of the RCBS Uniflow Powder Measure Drop Tube:

1. Installation:

- Ensure the powder measure is securely mounted to a stable surface using the standard 7/8 to 14 thread.
- Use the included bench or shelf bracket to stabilize the powder measure.
- Attach the appropriate drop tube for your caliber (22 caliber and up) to the measuring cylinder.

2. Usage:

- Before use, check that the measuring cylinder is clean and free from any obstructions.
- Adjust the numbered measuring screw to the desired charge weight.
- Slowly pour smokeless powder into the measuring cylinder, ensuring not to exceed the recommended fill level.
- Once filled, use the measuring screw to dispense the powder into your reloading case.
- After use, clean the measuring cylinder to prevent powder residue buildup.

Disposal Instructions

Proper disposal of the product and any associated materials is essential:

- Dispose of any unused or expired smokeless powder according to local regulations.
- Recycle packaging materials where possible.
- Do not dispose of the product in regular household waste. Follow local guidelines for hazardous materials.

Contact Information for Further Support

For any safety inquiries or additional support regarding the RCBS Uniflow Powder Measure Drop Tube, please refer to the manufacturer's contact details provided with your product packaging.

Thank you for your attention to these safety guidelines. Your safety is our priority, and we hope you enjoy using the RCBS Uniflow Powder Measure Drop Tube.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk