

# **BENCH/TRIMMER C CLAMP - REDDING BENCH STAND TRIMMER CLAMP**

[Reloading](#) > [Powder Handling](#) > [Powder Measures & Dispensers](#)

Double "C" Clamp is the ideal size for clamping the Redding powder measure stand and case trimmer to a bench top. Accommodates a bench thickness of up to 2-1/4". May be used to mount any number of tools. A very handy item for the reloading room.



## **Attributes**

- Name: [REDDING BENCH STAND TRIMMER CLAMP](#)
- Manufacturer: [REDDING](#)
- Product no.: 749003603
- Mfr. No.: 30520
- Delivery weight: 0.204kg
- Shipping height: 43mm
- Shipping width: 127mm
- Shipping length: 193mm
- UPC: 611760305207

## **Item details**

Made in USA

# Table of Contents

- Startpage
- Safety Instruction Guide for BENCH/TRIMMER C CLAMP
- About Us

# Safety Instruction Guide for BENCH/TRIMMER C CLAMP

## Introduction

Thank you for choosing the BENCH/TRIMMER C CLAMP from Redding. This product is designed to securely hold your Redding powder measure stand and case trimmer to your workbench. Please read this safety instruction guide carefully to ensure safe and effective use of the product.

## General Safety Guidelines

- Ensure that the product is used only for its intended purpose.
- Always inspect the clamp before use for any signs of wear or damage.
- Keep the clamp out of reach of children and vulnerable individuals.
- Use the clamp in a welllit and organized workspace.
- Follow all local regulations and guidelines regarding tool use and safety.

## Specific Safety Precautions for Use

- **Clamping Force:** Do not overtighten the clamp as this may damage your workbench or the clamp itself.
- **Bench Thickness:** Ensure that your workbench does not exceed the maximum thickness of 21/4" for safe clamping.
- **Secure Tools:** Always ensure that the tools being mounted are securely attached to prevent accidents.
- **Avoid Pinch Points:** Be cautious of fingers and other body parts when adjusting the clamp to avoid pinching.
- **Stability:** Ensure that the workbench is stable and does not wobble when using the clamp.

## Instructions for Installation and Usage

1. **Identify the Workbench Location:** Choose a flat, stable surface on your workbench for installation.
2. **Position the Clamp:** Place the clamp over the edge of the workbench, ensuring the base is flush against the surface.
3. **Adjust the Clamp:** Turn the handle to adjust the clamp to the desired tightness. Ensure it is secure but not overly tight.
4. **Mount Your Tools:** Attach your Redding powder measure stand or case trimmer to the clamp, ensuring it is securely held in place.
5. **Check Stability:** Before starting any work, check that the tools are stable and securely clamped.

## Disposal Instructions

- Dispose of the BENCH/TRIMMER C CLAMP in accordance with local waste disposal regulations.
- If the clamp is damaged and cannot be reused, consider recycling it where facilities exist.

## Contact Information for Further Support

For any safety inquiries or additional support regarding the BENCH/TRIMMER C CLAMP, please refer to the contact information provided on the packaging or visit the manufacturer's website.

## Conclusion

By following these safety instructions, you can ensure a safe and effective experience while using the BENCH/TRIMMER C CLAMP. Always prioritize safety and adhere to the guidelines outlined in this document. Thank you for your attention to safety!

# About Us

## Brownells Austria

**Brownells - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories**

[www.brownells.at](http://www.brownells.at)