

SINGLE STAGE PRESS STEEL SHOT CHARGE BAR - MEC RELOADING 1-1/2OZ #3-#6 SHOT SINGLE STAGE STEEL SHOT CHARGE BAR

[Reloading](#) > [Reloading Presses](#) > [Reloading Press Accessories](#)

This is a steel shot charge bar for single stage reloaders. Available to load from 7/8 oz. to 1-1/2 oz. of shot and #1 sizes down to #6.



Attributes

- Name: MEC RELOADING 1-1/2OZ #3-#6 SHOT SINGLE STAGE STEEL SHOT CHARGE BAR
- Manufacturer: MEC RELOADING
- Product no.: 749019393
- Mfr. No.: 30211236
- Size: 1-1/2 oz
- Delivery weight: 0.229kg
- Shipping height: 25mm
- Shipping width: 25mm
- Shipping length: 165mm
- UPC: 098489016735

Item details

Made in USA

Table of Contents

- Startpage
- Safety Instructions for the SINGLE STAGE PRESS STEEL SHOT CHARGE BAR MEC RELOADING 11/2OZ #3#6 SHOT
- About Us

Safety Instructions for the SINGLE STAGE PRESS STEEL SHOT CHARGE BAR MEC RELOADING 11/2OZ #3#6 SHOT

Introduction

Thank you for choosing the SINGLE STAGE PRESS STEEL SHOT CHARGE BAR from MEC RELOADING. This product is designed for single stage reloaders, allowing you to load shot sizes ranging from #1 to #6 and weights from 7/8 oz. to 11/2 oz. This safety instruction guide is intended to provide you with important information regarding the safe use, installation, and disposal of this product in compliance with the EU General Product Safety Regulation (GPSR).

General Safety Guidelines

- Ensure that the product is used only for its intended purpose.
- Always read and understand the instructions before using the product.
- Keep the product out of reach of children and vulnerable individuals.
- Regularly inspect the product for any signs of wear or damage before use.
- Report any unsafe product conditions or accidents to the appropriate authorities.
- Stay informed about product recalls through the EU Safety Gate platform.

Specific Safety Precautions for Use

- Always wear appropriate personal protective equipment (PPE) such as safety glasses and gloves while reloading.
- Never exceed the recommended load limits for the charge bar.
- Ensure that the reloading area is wellventilated to avoid inhalation of any dust or fumes.
- Avoid using the charge bar if you are under the influence of alcohol or drugs.
- Do not modify or alter the charge bar in any way as this may compromise safety.
- Follow all local laws and regulations regarding the use of reloading equipment and materials.

Instructions for Installation and Usage

1. Installation

- Ensure that the reloading press is on a stable, flat surface.
- Attach the charge bar to the reloading press according to the manufacturer's instructions.
- Secure all connections and ensure that the charge bar is firmly in place.

2. Usage

- Measure the desired amount of shot to be loaded (between 7/8 oz. and 11/2 oz.).
- Select the appropriate shot size (#1 to #6) for your reloading needs.
- Load the shot into the charge bar, ensuring it is properly seated.
- Operate the reloading press according to the manufacturer's instructions.
- After use, clean the charge bar to remove any residual shot or debris.

Disposal Instructions

- Dispose of any unused or damaged products in accordance with local waste disposal regulations.
- Do not dispose of the product in regular household waste.
- Consider recycling options if available in your area.

Contact Information for Further Support

For any further assistance or inquiries regarding the SINGLE STAGE PRESS STEEL SHOT CHARGE BAR, please consult the manufacturer's customer support or your local retailer.

Thank you for prioritizing safety while using the SINGLE STAGE PRESS STEEL SHOT CHARGE BAR. Your adherence to these guidelines helps ensure a safe and effective reloading experience.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk