

# **SINGLE STAGE PRESS STEEL SHOT CHARGE BAR - MEC RELOADING 1-1/8OZ #3-#6 SHOT SINGLE STAGE STEEL SHOT CHARGE BAR**

## [Reloading](#) > [Reloading Presses](#) > [Reloading Press Accessories](#)

This is a steel shot charge bar for single stage reloaders. Available to load from 7/8 oz. to 1-1/2 oz. of shot and #1 sizes down to #6.



## Attributes

- Name: MEC RELOADING 1-1/8OZ #3-#6 SHOT SINGLE STAGE STEEL SHOT CHARGE BAR
- Manufacturer: MEC RELOADING
- Product no.: 749019395
- Mfr. No.: 30211846
- Size: 1-1/8 oz
- Delivery weight: 0.236kg
- Shipping height: 25mm
- Shipping width: 25mm
- Shipping length: 165mm
- UPC: 098489010955

## Item details

Made in USA

# Table of Contents

- Startpage
- Safety Instruction Guide for SINGLE STAGE PRESS STEEL SHOT CHARGE BAR MEC RELOADING 11/8OZ #3#6 SHOT
- About Us

# Safety Instruction Guide for SINGLE STAGE PRESS STEEL SHOT CHARGE BAR MEC RELOADING

## 11/8OZ #3#6 SHOT

### Introduction

Thank you for purchasing the SINGLE STAGE PRESS STEEL SHOT CHARGE BAR by MEC RELOADING. This product is designed for single stage reloaders and allows you to load shot from 7/8 oz. to 11/2 oz., accommodating shot sizes from #1 to #6. To ensure safe and effective use, please read and follow the safety instructions outlined in this guide.

### General Safety Guidelines

- Always read the entire user manual before using the product.
- Ensure that the product is used only for its intended purpose.
- Keep the product out of reach of children and vulnerable individuals.
- Regularly inspect the product for any signs of wear or damage before use.
- Follow all local laws and regulations regarding the use of reloading equipment.
- If you notice any unusual sounds or malfunctions during use, stop immediately and inspect the product.
- Report any unsafe conditions or accidents to the appropriate authorities.

### Specific Safety Precautions for Use

- Wear appropriate personal protective equipment (PPE) such as safety glasses and gloves while reloading.
- Ensure the workspace is wellventilated to avoid inhalation of any dust or particles.
- Keep all tools and materials organized to prevent accidents during the reloading process.
- Do not exceed the maximum load specifications as indicated in the product guidelines.
- Avoid distractions while using the product to maintain focus and safety.
- Store the charge bar in a dry and secure location when not in use.

### Instructions for Installation and Usage

#### Installation

1. **Unpack the Charge Bar:** Carefully remove the charge bar from its packaging.
2. **Inspect the Product:** Check for any visible damage or missing parts.
3. **Mounting:**
  - Securely attach the charge bar to your reloading press according to the manufacturer's instructions.
  - Ensure that all bolts and screws are tightened to prevent movement during use.

#### Usage

1. **Setting the Charge Bar:**
  - Adjust the charge bar to the desired shot weight (between 7/8 oz. and 11/2 oz.) using the provided adjustment mechanism.
  - Confirm the shot size setting is between #1 and #6.
2. **Loading the Shot:**
  - Carefully pour the appropriate amount of shot into the charge bar.
  - Ensure that the shot is evenly distributed and does not exceed the maximum load.
3. **Operating the Reloading Press:**
  - Follow the reloading press's specific instructions for operation.
  - Monitor the reloading process closely to ensure consistent performance.

#### 4. PostUse Care:

- After use, clean the charge bar to remove any residue or buildup.
- Store the charge bar in a safe location away from moisture and extreme temperatures.

## Disposal Instructions

- Dispose of any unused or expired materials in accordance with local regulations.
- Ensure that the charge bar itself is disposed of in an environmentally responsible manner, considering recycling options where available.
- Do not dispose of the product in regular household waste if it contains hazardous materials.

## Contact Information for Further Support

For any inquiries or further assistance regarding the SINGLE STAGE PRESS STEEL SHOT CHARGE BAR, please contact the manufacturer or your local distributor. It is important to have a reliable point of contact for any safety concerns or product issues.

By following these safety instructions, you can ensure a safe and effective reloading experience with your SINGLE STAGE PRESS STEEL SHOT CHARGE BAR. Always prioritize safety and adhere to all guidelines for optimal use. Thank you for choosing MEC RELOADING.

# About Us

## Brownells UK

### **Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories**

Unit 1, Laughing Dog Industrial Estate  
London Road  
Rugby  
Warwickshire  
CV23 9LP

[www.brownells.co.uk](http://www.brownells.co.uk)