

SINGLE STAGE PRESS STEEL SHOT CHARGE BAR - MEC RELOADING 1-3/8OZ #3-#6 SHOT SINGLE STAGE STEEL SHOT CHARGE BAR

[Reloading](#) > [Reloading Presses](#) > [Reloading Press Accessories](#)

This is a steel shot charge bar for single stage reloaders. Available to load from 7/8 oz. to 1-1/2 oz. of shot and #1 sizes down to #6.



Attributes

- Name: MEC RELOADING 1-3/8OZ #3-#6 SHOT SINGLE STAGE STEEL SHOT CHARGE BAR
- Manufacturer: MEC RELOADING
- Product no.: 749019396
- Mfr. No.: 30213836
- Size: 1-3/8 oz
- Delivery weight: 0.231kg
- Shipping height: 25mm
- Shipping width: 25mm
- Shipping length: 165mm
- UPC: 098489015677

Item details

Made in USA

Table of Contents

- Startpage
- Safety Instruction Guide for SINGLE STAGE PRESS STEEL SHOT CHARGE BAR MEC RELOADING 13/8OZ #3#6 SHOT
- About Us

Safety Instruction Guide for SINGLE STAGE PRESS STEEL SHOT CHARGE BAR MEC RELOADING 13/8OZ #3#6 SHOT

Introduction

Thank you for choosing the SINGLE STAGE PRESS STEEL SHOT CHARGE BAR from MEC RELOADING. This product is designed for single stage reloaders, allowing you to load shot sizes from #1 down to #6, and weights from 7/8 oz. to 11/2 oz. This guide provides important safety instructions to ensure the safe and effective use of your steel shot charge bar.

General Safety Guidelines

- Ensure that the product is used in accordance with the manufacturer's instructions to prevent accidents and injuries.
- Keep the charge bar and all reloading equipment out of reach of children and vulnerable individuals.
- Regularly inspect the charge bar for wear and damage before each use.
- Store the product in a dry and safe location when not in use.
- Report any unsafe conditions or accidents to the relevant authorities.

Specific Safety Precautions for Use

- Always wear appropriate personal protective equipment (PPE), including safety glasses and gloves, while reloading.
- Do not exceed the recommended load limits of 11/2 oz. for the charge bar.
- Ensure that you are familiar with the operation of your reloading press before using the charge bar.
- Avoid distractions while reloading to maintain focus and safety.
- Do not attempt to modify the charge bar or use it in a manner not intended by the manufacturer.

Instructions for Installation and Usage

1. Installation:

- Ensure the reloading press is securely mounted and stable.
- Clean the mounting area of the press before installation.
- Align the charge bar with the press according to the manufacturer's guidelines.
- Secure the charge bar in place using the provided fasteners.

2. Usage:

- Set the desired shot weight by adjusting the charge bar according to the instructions.
- Load the appropriate shot size into the charge bar.
- Carefully operate the reloading press, following the manufacturer's instructions for reloading ammunition.
- After reloading, check the completed rounds for quality and consistency.

Disposal Instructions

- Dispose of any damaged or worn charge bars in accordance with local regulations for metal waste.
- Recycle materials whenever possible to minimize environmental impact.
- Do not dispose of the charge bar in regular household waste.

Contact Information for Further Support

For any inquiries or assistance regarding the SINGLE STAGE PRESS STEEL SHOT CHARGE BAR, please refer to the manufacturer's contact information provided with the product.

By following these safety guidelines and instructions, you can ensure a safe and effective reloading experience with your SINGLE STAGE PRESS STEEL SHOT CHARGE BAR. Thank you for prioritizing safety in your reloading activities.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk