

STEEL SHOT CHARGE BAR - MEC RELOADING 1-1/2OZ BB-#2 STEEL SHOT CHARGE BAR

[Reloading](#) > [Reloading Presses](#) > [Reloading Press Accessories](#)

This is a steel shot charge bar for single stage reloaders. Available to load from 7/8 oz. to 1-1/2 oz. of shot and BB sizes down to #3.



Attributes

- Name: [MEC RELOADING 1-1/2OZ BB-#2 STEEL SHOT CHARGE BAR](#)
- Manufacturer: [MEC RELOADING](#)
- Product no.: 749019398
- Mfr. No.: 302112BB2
- Size: 1-1/2 oz
- Delivery weight: 0.229kg
- Shipping height: 25mm
- Shipping width: 25mm
- Shipping length: 165mm
- UPC: 098489014021

Item details

Made in USA

Table of Contents

- [Startpage](#)
- [Safety Instruction Guide for STEEL SHOT CHARGE BAR MEC RELOADING 11/20Z BB#2 STEEL SHOT CHARGE BAR](#)
- [About Us](#)

Safety Instruction Guide for STEEL SHOT CHARGE BAR MEC RELOADING 11/2OZ BB#2 STEEL SHOT CHARGE BAR

Introduction

Thank you for choosing the STEEL SHOT CHARGE BAR MEC RELOADING 11/2OZ BB#2 STEEL SHOT CHARGE BAR. This product is designed for use with single stage reloaders, allowing you to load shot weights ranging from 7/8 oz. to 11/2 oz. and BB sizes down to #3. For your safety and to ensure optimal performance, please read this guide carefully before using the product.

General Safety Guidelines

- Always use the product in accordance with the manufacturer's instructions.
- Ensure that the product is suitable for your specific reloading equipment.
- Keep the product out of reach of children and vulnerable individuals.
- Regularly inspect the product for any signs of wear or damage before use.
- Report any unsafe conditions or incidents to the relevant authorities.
- Stay informed about product recalls by checking the EU's Safety Gate platform.

Specific Safety Precautions for Use

- Always wear appropriate personal protective equipment (PPE), including safety glasses and gloves, when handling reloading components.
- Avoid direct contact with steel shot and other reloading materials to prevent injury.
- Do not exceed the recommended load weights as specified by the manufacturer.
- Ensure that your workspace is clean and free from obstructions to prevent accidents.
- Follow all local laws and regulations regarding the use and storage of reloading materials.

Instructions for Installation and Usage

1. Installation:

- Ensure that your reloading press is properly set up and secured.
- Carefully insert the STEEL SHOT CHARGE BAR into the designated slot of your reloading press.
- Verify that the charge bar is securely in place and functioning correctly before proceeding.

2. Usage:

- Measure the desired amount of shot using the charge bar, ensuring it is set to the correct weight (between 7/8 oz. and 11/2 oz.).
- Load the shot into the appropriate hull or container.
- Follow your reloading press's instructions for completing the reloading process.
- After use, clean the charge bar and reloading press to maintain optimal performance.

Disposal Instructions

- Dispose of any unused or damaged reloading materials in accordance with local regulations.
- Recycle the packaging materials where possible.
- Do not dispose of steel shot or other reloading components in regular waste; check local guidelines for hazardous materials disposal.

Contact Information for Further Support

For any questions or concerns regarding the safety and use of the STEEL SHOT CHARGE BAR, please refer to the manufacturer's contact information provided with the product packaging. You can also consult the EU's Safety Gate platform for additional safety resources and product updates.

Thank you for your attention to these safety guidelines. Your careful use of the STEEL SHOT CHARGE BAR will help ensure a safe and enjoyable reloading experience.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk