

STEEL SHOT CHARGE BAR - MEC RELOADING 1-1/4OZ BB-#2 STEEL SHOT CHARGE BAR

[Reloading](#) > [Reloading Presses](#) > [Reloading Press Accessories](#)

This is a steel shot charge bar for single stage reloaders. Available to load from 7/8 oz. to 1-1/2 oz. of shot and BB sizes down to #3.



Attributes

- Name: [MEC RELOADING 1-1/4OZ BB-#2 STEEL SHOT CHARGE BAR](#)
- Manufacturer: [MEC RELOADING](#)
- Product no.: 749019399
- Mfr. No.: 302114BB2
- Size: 1-1/4 oz
- Delivery weight: 0.234kg
- Shipping height: 25mm
- Shipping width: 25mm
- Shipping length: 165mm
- UPC: 098489013994

Item details

Made in USA

Table of Contents

- Startpage
- Safety Instruction Guide for STEEL SHOT CHARGE BAR MEC RELOADING 11/4OZ BB#2 STEEL SHOT CHARGE BAR
- About Us

Safety Instruction Guide for STEEL SHOT CHARGE BAR MEC RELOADING 11/4OZ BB#2 STEEL SHOT CHARGE BAR

Introduction

Thank you for choosing the STEEL SHOT CHARGE BAR MEC RELOADING 11/4OZ BB#2. This product is designed for use with single stage reloaders and is capable of loading shot weights from 7/8 oz. to 11/2 oz., including BB sizes down to #3. To ensure safe and effective use, please read this safety instruction guide carefully.

General Safety Guidelines

- Always use the product according to the manufacturer's instructions.
- Keep this product out of reach of children and vulnerable individuals.
- Inspect the product before each use for any signs of damage or wear.
- Do not modify the product in any way.
- Report any unsafe products or incidents to the appropriate authorities.

Specific Safety Precautions for Use

- Ensure that you are familiar with the reloading process and the specific requirements for your reloader.
- Use appropriate personal protective equipment (PPE), such as safety glasses and gloves, when handling materials.
- Avoid using the charge bar in wet or damp conditions to prevent rust and corrosion.
- Store the charge bar in a cool, dry place when not in use.
- Be cautious of sharp edges and moving parts during operation.

Instructions for Installation and Usage

1. Installation:

- Ensure the reloader is turned off and unplugged before installation.
- Attach the steel shot charge bar securely to the reloader according to the manufacturer's specifications.
- Doublecheck that all connections are tight and that there are no obstructions.

2. Usage:

- Confirm that the charge bar is set to the desired shot weight before loading.
- Carefully load the shot into the charge bar, ensuring no spills or overloading occur.
- Follow the reloader's manual for specific instructions on operating the machine with the charge bar.
- After use, clean the charge bar to remove any residue or debris.

Disposal Instructions

- Dispose of the product in accordance with local regulations.
- If the product is no longer usable, consider recycling it if possible.
- Do not dispose of the product in household waste if it contains hazardous materials.

Contact Information for Further Support

For any inquiries regarding the safety and handling of this product, please refer to the manufacturer's contact information provided on the product packaging or documentation. Always ensure you have the latest safety updates and product recalls.

Thank you for your attention to these safety instructions. Your safety is our priority, and we hope you enjoy using the STEEL SHOT CHARGE BAR MEC RELOADING 11/4OZ BB#2.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk