

PROGRESSIVE STAGE PRESS LEAD SKEET SPECIAL CHARGE BAR - MEC RELOADING 7/8OZ PROGRESSIVE STAGE LEAD SKEET SPECIAL CHARGE BAR

[Reloading](#) > [Reloading Presses](#) > [Reloading Press Accessories](#)

Lead shot bars designed for progressive reloaders. Available to load 1/2 oz. to 1-1/8 oz.



Attributes

- Name: [MEC RELOADING 7/8OZ PROGRESSIVE STAGE LEAD SKEET SPECIAL CHARGE BAR](#)
- Manufacturer: [MEC RELOADING](#)
- Product no.: 749019442
- Mfr. No.: 50278SS
- Size: 7/8 oz
- Delivery weight: 0.243kg
- Shipping height: 25mm
- Shipping width: 25mm
- Shipping length: 165mm
- UPC: 098489013956

Item details

Made in USA

Table of Contents

- Startpage
- Safety Instruction Guide for PROGRESSIVE STAGE PRESS LEAD SKEET SPECIAL CHARGE BAR
- About Us

Safety Instruction Guide for PROGRESSIVE STAGE PRESS LEAD SKEET SPECIAL CHARGE BAR

Introduction

Thank you for choosing the PROGRESSIVE STAGE PRESS LEAD SKEET SPECIAL CHARGE BAR by MEC RELOADING. This product is designed for progressive reloaders and is intended for loading lead shot from 1/2 oz. to 11/8 oz. This safety instruction guide provides essential information to ensure safe usage and compliance with the EU General Product Safety Regulation (GPSR).

General Safety Guidelines

- Ensure that the product is used only for its intended purpose as specified in the product description.
- Always read and understand the user manual before using the product.
- Keep the product out of reach of children and vulnerable individuals.
- Regularly check for any signs of wear or damage before use.
- Report any unsafe conditions or incidents to the appropriate authorities.
- Stay informed about product recalls and safety alerts through the EU's Safety Gate platform.

Specific Safety Precautions for Use

- Always wear appropriate safety gear, including eye protection and gloves, when handling materials for reloading.
- Ensure that the work area is wellventilated to avoid inhalation of dust or fumes.
- Do not exceed the maximum load specifications for the charge bar.
- Keep the work area clean and free of obstructions to prevent accidents.
- Avoid distractions while reloading to maintain focus and ensure safety.
- Store the charge bar in a dry place, away from moisture and extreme temperatures.

Instructions for Installation and Usage

1. Installation:

- Ensure the reloading press is turned off and unplugged before installation.
- Follow the manufacturer's instructions for attaching the charge bar to the reloading press securely.
- Doublecheck all connections to ensure they are secure before use.

2. Usage:

- Measure the desired amount of lead shot accurately before loading.
- Use the charge bar only with compatible MEC RELOADING equipment.
- Follow the reloading process as outlined in the user manual, ensuring each step is completed correctly.
- Monitor the reloading process closely to detect any issues early.

Disposal Instructions

- Dispose of any unused or expired materials in accordance with local regulations.
- Do not dispose of the product in regular household waste.
- Contact local waste management authorities for proper disposal methods for hazardous materials.

Contact Information for Further Support

For any questions or concerns regarding the PROGRESSIVE STAGE PRESS LEAD SKEET SPECIAL CHARGE BAR, please refer to the manufacturer's contact information provided with the product packaging or user manual.

By following these guidelines, you can ensure a safe and efficient reloading experience. Thank you for prioritizing safety in your reloading activities.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk