

Zero-Max Shooting Rest

[Shooting Accessories](#) > [Shooting Rests](#) > [Rifle Rests](#)

The Caldwell® ZeroMax™ Shooting Rest is a full-length metal rest that comes packed with all of the features that today's shooters demand. This "no-frills" full-length rest offers the shooter a rock-solid platform for quick and convenient set-up without the expense and complexity of other rests.

NO IMAGE
AVAILABLE

Attributes

- Name: [Zero-Max Shooting Rest](#)
- Manufacturer: [Caldwell](#)
- Product no.: EU1001846
- Mfr. No.: 546889
- Delivery weight: 2.38kg
- Shipping height: 175mm
- Shipping width: 137mm
- Shipping length: 617mm
- UPC: 661120468899

Table of Contents

- Startpage
- Caldwell ZeroMax Shooting Rest Safety Instructions
- About Us

Caldwell ZeroMax Shooting Rest Safety Instructions

Introduction

Thank you for choosing the Caldwell® ZeroMax™ Shooting Rest. This manual provides essential safety instructions and guidelines to ensure the safe and effective use of your shooting rest. Please read this guide carefully before use to maximize safety and performance.

General Safety Guidelines

- Always handle firearms with care and respect. Ensure that all safety protocols are followed.
- Use the shooting rest only for its intended purpose as specified in this manual.
- Keep the shooting rest out of reach of children and vulnerable individuals.
- Inspect the shooting rest before each use for any signs of damage or wear. Do not use if damaged.
- Store the shooting rest in a dry place away from moisture and extreme temperatures.
- Report any unsafe products or accidents to the appropriate authorities and check for recall updates on the EU's Safety Gate platform.

Specific Safety Precautions for Use

- Ensure that the shooting rest is placed on a stable and level surface before use.
- Always ensure that the firearm is unloaded when setting up the shooting rest.
- Do not exceed the weight limit of the shooting rest. Refer to the product specifications for details.
- Avoid placing any part of your body in front of the firearm when it is mounted on the rest.
- Never leave a loaded firearm unattended on the shooting rest.
- Use proper eye and ear protection while shooting.

Instructions for Installation and Usage

1. Setup

- Unpack the shooting rest carefully and ensure all components are present.
- Place the shooting rest on a flat, stable surface.
- Adjust the height of the rest as needed to align with your shooting position.

2. Mounting the Firearm

- Ensure the firearm is unloaded before mounting.
- Securely rest the firearm on the designated area of the shooting rest.
- Adjust the firearm position for optimal stability and aim.

3. Using the Shooting Rest

- Once the firearm is securely mounted, assume your shooting position.
- Ensure that the area around you is clear of obstructions and bystanders before firing.
- After shooting, always check the firearm and ensure it is safe before removing it from the rest.

4. PostUse Care

- After use, clean the shooting rest as needed to remove dirt and debris.
- Store the shooting rest in a safe location, away from children and unauthorized users.

Disposal Instructions

- When the shooting rest reaches the end of its life cycle, dispose of it in accordance with local regulations.
- Do not dispose of the product in regular household waste. Check for recycling options or special disposal facilities for metal products.

Contact Information for Further Support

For any questions or concerns regarding the Caldwell® ZeroMax™ Shooting Rest, please refer to the manufacturer's contact information provided with your product packaging.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk