

REPLACEMENT CYLINDER POINTS - CRATEX POINT, COARSE, #6 CYL, 1/16" ARBOR

[Gunsmith Tools](#) > [Power Tools & Accessories](#) > [Rubber Abrasive Tools](#) > [Rubber Abrasive Cylinder Points](#)

Preshaped Abrasive Wheels For All Polishing/Grinding Needs

Bulk replacements sold 25 each per pkg. #6 Cylinder Point, $\frac{1}{4}$ " (6.3mm) diameter, $\frac{7}{8}$ " (22.2mm) long.



Attributes

- Name: [CRATEX POINT, COARSE, #6 CYL, 1/16" ARBOR](#)
- Manufacturer: [CRATEX](#)
- Product no.: 190025061
- Mfr. No.: 6
- Delivery weight: 0.045kg
- Shipping width: 83mm
- Shipping length: 146mm

Table of Contents

- Startpage
- Safety Instruction Guide for REPLACEMENT CYLINDER POINTS CRATEX POINT, COARSE, #6 CYL, 1/16" ARBOR
- About Us

Safety Instruction Guide for REPLACEMENT CYLINDER POINTS CRATEX POINT, COARSE, #6 CYL, 1/16" ARBOR

Introduction

Thank you for choosing the REPLACEMENT CYLINDER POINTS CRATEX POINT. This guide provides essential safety instructions to ensure the safe use and handling of this product. Please read this guide carefully before using the product.

General Safety Guidelines

- Always use the product as intended and in accordance with the manufacturer's instructions.
- Keep the product out of reach of children and vulnerable individuals.
- Regularly check for any signs of wear or damage before use.
- If any part of the product appears damaged, discontinue use immediately and contact the manufacturer.
- Report any unsafe products or accidents to the relevant authorities.

Specific Safety Precautions for Use

- Wear appropriate personal protective equipment (PPE) such as safety goggles and gloves when using the product.
- Ensure that the working area is clean and free from hazards.
- Do not exceed the recommended operating speed to avoid potential injury or product failure.
- Avoid using the product near flammable materials.
- Be cautious of dust and debris generated during use; consider using a dust mask if necessary.

Instructions for Installation and Usage

1. Installation:

- Ensure the power tool is turned off and unplugged before installing the cylinder point.
- Remove any existing attachments from the tool.
- Insert the #6 cylinder point into the tool's arbor, ensuring a secure fit.
- Tighten the arbor nut to secure the cylinder point firmly in place.

2. Usage:

- Always inspect the cylinder point before use for any signs of wear or damage.
- Start the power tool at a low speed to ensure stability.
- Gradually increase the speed as needed for your application.
- Maintain a firm grip on the tool and direct the cylinder point away from your body.
- After use, turn off the power tool and allow it to come to a complete stop before removing the cylinder point.

Disposal Instructions

- Dispose of the product in accordance with local regulations.
- Do not dispose of the product in regular household waste.
- Consider recycling options where available.

Contact Information for Further Support

For any safety inquiries or product support, please refer to the manufacturer's contact information provided on the packaging or product documentation.

Thank you for prioritizing safety while using the REPLACEMENT CYLINDER POINTS CRATEX POINT. Your adherence to these guidelines helps ensure a safe and effective experience.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk