

LEADER CHECKERING SET - GUNLINE LEADER SET,20 LPI

[Gunsmith Tools & Supplies](#) > [Stock Work & Finishing](#) > [Hand Checkering Tools](#) > [Checkering Sets](#)

Positive, Spring-Pinned Heads, Smooth Cutting, Long Lasting

Affordable and easily expanded as skill level increases.



Attributes

- Name: [GUNLINE LEADER SET,20 LPI](#)
- Manufacturer: [GUNLINE](#)
- Product no.: 364500520
- Mfr. No.: LE-20
- Size: 20 LPI
- Delivery weight: 0.204kg
- UPC: 818262201031

Item details

Made in USA

Table of Contents

- Startpage
- LEADER CHECKERING SET GUNLINE LEADER SET, 20 LPI Safety Instruction Guide
- About Us

LEADER CHECKERING SET GUNLINE LEADER SET, 20 LPI Safety Instruction Guide

Introduction

Thank you for choosing the LEADER CHECKERING SET GUNLINE LEADER SET, 20 LPI. This product is designed to enhance your skill in checkering while ensuring safety during use. Please read this safety instruction guide carefully to understand how to use the tools safely and effectively.

General Safety Guidelines

- Always use the tools in a welllit and clutterfree workspace.
- Keep the tools out of reach of children and pets when not in use.
- Wear appropriate personal protective equipment (PPE), including safety glasses and gloves.
- Inspect all tools for damage before use. Do not use damaged tools.
- Follow all instructions provided in this guide to minimize risks.
- Be aware of your surroundings and ensure that no one is in close proximity while you are using the tools.

Specific Safety Precautions for Use

- **Cutting Tools:**
 - Handle cutting tools with care to avoid cuts and injuries.
 - Always cut away from your body and keep fingers clear of cutting edges.
- **Edge Spacer and VEdger:**
 - Ensure that the edge spacers are securely attached before use.
 - Do not apply excessive force; let the tool do the work.
- **Checkering Rule and Layout Gauge:**
 - Use only on stable surfaces to prevent slipping.
 - Ensure that the workpiece is securely clamped before marking or cutting.
- **Illustrated Instructions:**
 - Follow the illustrated instructions closely to avoid improper use of tools.

Instructions for Installation and Usage

1. Preparation:

- Choose a clean, stable work surface.
- Gather all tools included in the set: 2Edge Spacer, BorderVex, VEdger, Pointer Long, Checkerer's Rule, Layout Gauge, illustrated instructions, 60° spacers, and 90° cutters.

2. Setting Up:

- Secure the workpiece firmly to the work surface using clamps.
- Select the appropriate tool based on the task at hand.

3. Using the Tools:

- Refer to the illustrated instructions for specific guidance on using each tool.
- Start with the edge spacer to create initial lines.
- Use the VEdger for precise cutting along the marked lines.
- Follow up with the Pointer Long for detailing work.

4. After Use:

- Clean all tools after use to remove any debris.
- Store tools in a safe, dry location away from children.

Disposal Instructions

- Dispose of any damaged tools in accordance with local regulations.
- Do not throw tools in regular trash if they are sharp or could pose a safety risk.
- Consider recycling options for metal parts if applicable.

Contact Information for Further Support

For any safety inquiries or concerns regarding the LEADER CHECKERING SET GUNLINE LEADER SET, 20 LPI, please contact the manufacturer or an authorized retailer. Always refer to the EU Safety Gate platform for updates on product safety and recalls.

Thank you for following these safety instructions. Your safety is our priority, and we wish you success in your checkering projects!

About Us

Brownells Europe

Brownells Europe - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

P.O.Box 4300
Warwick
CV34 9BR

www.brownells.eu