

HENRY GHOST RING SIGHTS - XS SIGHT SYSTEMS GHOST RING WS FOR LEVER RAIL HENRY 45-70 SCREW ON FS

[Rifle Parts](#) > [Sights](#) > [Front Sights](#)

The XS Ghost Ring WS hunting sights pairs with XS Lever Rail HN-6000R-N to offer improved accuracy and faster sight acquisition in a rugged all-steel design. Fits Henry .45-70 with round barrel and screw on front sight. Does not fit models with front sight blade dovetailed directly into the barrel. Precision machined in Fort Worth, TX. XS Ghost Ring WS is fully adjustable for windage and elevation and comes with two apertures, .230" and .191" inside diameter, for different lighting conditions. The large Ghost Ring affords great field of view for fast target acquisition. The XS White Stripe (WS) front sight replaces the existing blade and ramp and features a blued steel body with a painted white stripe face. White on black front post is highly visible in all lighting conditions, as well as provides contrast against any color background. Due to moving the rear sight from the barrel to the receiver, some zeroing issues might arise. Alternate front sight heights are available and covered under XS' No Questions Asked Warranty. For use with Lever Rail only.



Attributes

- Name: [XS SIGHT SYSTEMS GHOST RING WS FOR LEVER RAIL HENRY 45-70 SCREW ON FS](#)
- Manufacturer: [XS SIGHT SYSTEMS](#)
- Product no.: 430109172
- Mfr. No.: HN-0001-5
- Colour: Black
- Material: Steel
- Model: X Model, Big Boy
- Style: Post
- Weapon type: Henry
- Delivery weight: 0.113kg
- Shipping height: 32mm
- Shipping width: 127mm
- Shipping length: 203mm
- UPC: 647533018944

Item details

Made in USA

Table of Contents

- Startpage
- Safety Instruction Guide for HENRY GHOST RING SIGHTS XS SIGHT SYSTEMS GHOST RING WS FOR LEVER RAIL HENRY 4570 SCREW ON FS
- About Us

Safety Instruction Guide for HENRY GHOST RING SIGHTS XS SIGHT SYSTEMS GHOST RING WS FOR LEVER RAIL HENRY 4570 SCREW ON FS

Introduction

Thank you for choosing the HENRY GHOST RING SIGHTS XS SIGHT SYSTEMS GHOST RING WS. This product is designed to enhance your shooting experience by providing improved accuracy and faster sight acquisition. However, it is essential to follow safety guidelines to ensure safe usage and optimal performance. This guide outlines important safety instructions, precautions, and information regarding the installation and use of the product.

General Safety Guidelines

- Always handle firearms and related accessories with care and responsibility.
- Ensure that you are familiar with the operation of your firearm before using this sight system.
- Follow all local laws and regulations regarding the use of firearms and firearm accessories.
- Keep the product out of reach of children and unauthorized users.
- Regularly inspect the sight system for any signs of wear or damage before each use.
- If you notice any abnormalities, do not use the product and seek professional assistance.

Specific Safety Precautions for Use

- Ensure that the sight is properly installed according to the instructions provided in this guide.
- Do not attempt to modify or alter the sight in any way.
- Use only the recommended front sight heights for your specific model to avoid zeroing issues.
- Be aware that moving the rear sight from the barrel to the receiver may lead to some zeroing challenges.
- Always wear appropriate eye protection when using firearms equipped with this sight.
- Avoid using the sight in extreme weather conditions that may affect visibility or performance.

Instructions for Installation and Usage

Installation

1. **Gather Required Tools:** Ensure you have the necessary tools for installation, including a screwdriver suitable for the screws provided with the sight system.
2. **Remove Existing Front Sight:** Carefully remove the existing front sight from your Henry .4570 firearm.
3. **Install XS Ghost Ring WS:**
 - Align the XS Ghost Ring WS with the mounting area on the lever rail.
 - Securely attach the sight using the provided screws, ensuring it is tight but not overtightened to avoid damage.
4. **Adjust for Windage and Elevation:**
 - Use the adjustment mechanisms to set the windage and elevation according to your shooting preferences.
 - Test the adjustments at the range to ensure accuracy.

Usage

- Before shooting, ensure that the sight is properly zeroed.
- Select the appropriate aperture size (.230" or .191") based on the lighting conditions for optimal visibility.
- Practice using the sight in a controlled environment before using it in the field.
- Regularly check the sight alignment and make adjustments as necessary.

Disposal Instructions

- Dispose of the product in accordance with local regulations for electronic and metal waste.
- Do not throw the product in regular household waste.
- If the product is damaged beyond repair, consult local waste management guidelines for proper disposal methods.

Contact Information for Further Support

For any inquiries regarding safety, installation, or use of the HENRY GHOST RING SIGHTS XS SIGHT SYSTEMS GHOST RING WS, please refer to the manufacturer's customer support resources or website.

By following these safety instructions, you can ensure a safe and enjoyable experience with your HENRY GHOST RING SIGHTS XS SIGHT SYSTEMS GHOST RING WS. Always prioritize safety and responsible usage when handling firearms and related accessories.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk