

# POWDER HANDLING STARTER SET - LYMAN POWDER HANDLING STARTER SET

[Reloading](#) > [Reloading Kits](#)

If you are new to reloading, you will need reliable and accurate powder handling equipment. The Powder Handling Starter Set gives you all the performance and accuracy you will need. The set includes the Pocket Touch 1500 Digital Scale, the E-ZEE Flo Universal Powder Trickler, and a Universal Loading Block. The Pocket Touch scale features 1500 grain capacity, an easy-to-read lighted display, hinged dust cover and auto shut-off. The scale also comes with a Universal Funnel Pan which combines a pouring spout and a funnel which accepts cases from 20 to 50 caliber, and a handy powder scoop. The E-ZEE Flo trickler is fully adjustable to work with any scale and allows you to bring your charges up smoothly and accurately to your exact desired charge weight. FEATURES: Touch 1500 Digital Scale – Provides 1500 grain capacity, an easy-to-read lighted display, Auto shut-off, and touch screen controls. Operates on two AAA batteries. E-ZEE Flo Universal Powder Trickler – Adjusts for height and comes with a feed tube extension to work with any scale. Universal Loading Block – An essential accessory to hold your cases when charged with powder. Prevents cases from tipping over and spilling powder. Works with rifle or pistol cases from 22 to 45 caliber.



## Attributes

- Name: [LYMAN POWDER HANDLING STARTER SET](#)
- Manufacturer: [LYMAN](#)
- Product no.: 430110547
- Mfr. No.: 7810322
- Delivery weight: 0.907kg
- Shipping height: 165mm
- Shipping width: 197mm
- Shipping length: 260mm
- UPC: 011516703224

## Item details

Made in USA

# Table of Contents

- [Startpage](#)
- [POWDER HANDLING STARTER SET Safety Instruction Guide](#)
- [About Us](#)

# POWDER HANDLING STARTER SET Safety Instruction Guide

## Introduction

Thank you for choosing the Lyman Powder Handling Starter Set. This guide provides essential safety instructions to ensure safe handling and operation of the equipment included in your set. Please read this document carefully before using the products.

## General Safety Guidelines

- Always handle all components with care to avoid damage and ensure safe operation.
- Keep the products out of reach of children and vulnerable individuals.
- Ensure that your workspace is clean, welllit, and free from distractions.
- Regularly inspect your equipment for any signs of wear or damage before use.
- Store all components in a safe and dry environment to prevent deterioration.
- Be aware of your surroundings and avoid using the equipment in areas with flammable materials.

## Specific Safety Precautions for Use

- **Pocket Touch 1500 Digital Scale:**

- Do not overload the scale beyond its 1500 grain capacity.
- Ensure the scale is placed on a flat, stable surface before use.
- Avoid exposure to moisture or extreme temperatures.
- Use the scale only for its intended purpose—measuring powder and similar materials.

- **EZEE Flo Universal Powder Trickler:**

- Adjust the height of the trickler carefully to avoid spills.
- Always use the trickler in conjunction with the Pocket Touch scale for accurate measurements.
- Do not attempt to modify or repair the trickler if it malfunctions.

- **Universal Loading Block:**

- Use the loading block to hold only the cases you are currently working with.
- Avoid overfilling the block to prevent tipping and spills.
- Ensure that the block is placed on a secure and stable surface.

## Instructions for Installation and Usage

- **Setting Up the Pocket Touch 1500 Digital Scale:**

1. Remove the scale from its packaging and place it on a flat surface.
2. Insert two AAA batteries into the battery compartment.
3. Press the power button to turn on the scale.
4. Allow the scale to warm up for a few seconds before use.
5. Use the tare function to reset the scale to zero before weighing your powder.

- **Using the EZEE Flo Universal Powder Trickler:**

1. Attach the feed tube extension if necessary.
2. Position the trickler above the scale's pan.

3. Adjust the height as needed for comfortable operation.
4. Gradually turn the adjustment knob to release powder into the pan.

- **Loading Cases with the Universal Loading Block:**

1. Place the loading block on a stable surface.
2. Insert cases into the block, ensuring they are secure and upright.
3. Carefully charge each case with powder, avoiding spills.
4. Once charged, remove the cases one at a time to prevent tipping.

## **Disposal Instructions**

- Dispose of any packaging materials in accordance with local recycling regulations.
- If any component becomes damaged or is no longer usable, follow local waste disposal guidelines for hazardous materials.
- Do not dispose of the equipment in regular household waste. Check for electronic waste disposal options in your area.

## **Contact Information for Further Support**

For any inquiries regarding safety, usage, or product issues, please refer to the contact information provided with your product packaging or visit the manufacturer's website for support resources.

## **Conclusion**

By following these safety instructions, you can ensure safe and effective use of the Lyman Powder Handling Starter Set. Always prioritize safety while reloading and handling powder. Thank you for your attention to these guidelines. Enjoy your reloading experience!

# About Us

## Brownells UK

### **Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories**

Unit 1, Laughing Dog Industrial Estate  
London Road  
Rugby  
Warwickshire  
CV23 9LP

[www.brownells.co.uk](http://www.brownells.co.uk)