

RELOADING SCALE KIT - MEC RELOADING RELOADING SCALE KIT

[Reloading](#) > [Powder Handling](#) > [Powder Scales](#)

Accurate and Consistent Loads Every Time

The Reloading Scale Kit from MEC Reloading gives you everything you need to accurately weigh your loads. The scale has a 100g capacity and 0.1 grain resolution. The Reloading Scale Kit is powered by two (2) AAA batteries. (Not included) Scale Pan 100g calibration weight The Reloading Scale Kit from MEC reloading helps to ensure accurate and consistent weights every time.



Attributes

- Name: [MEC RELOADING RELOADING SCALE KIT](#)
- Manufacturer: [MEC RELOADING](#)
- Product no.: 749017310
- Mfr. No.: 1078
- Delivery weight: 0.313kg
- Shipping height: 32mm
- Shipping width: 197mm
- Shipping length: 254mm
- UPC: 098489039383

Table of Contents

- Startpage
- Safety Instructions for MEC Reloading Scale Kit
- About Us

Safety Instructions for MEC Reloading Scale Kit

Introduction

Thank you for choosing the MEC Reloading Scale Kit. This guide provides essential safety instructions to ensure the safe and effective use of your reloading scale. Please read this document carefully before using the product to understand how to operate it safely and responsibly.

General Safety Guidelines

- Ensure that the Reloading Scale Kit is used in a dry and stable environment to prevent damage.
- Keep the scale and its components out of reach of children and pets.
- Always use the scale on a flat, stable surface to ensure accurate readings.
- Do not expose the scale to extreme temperatures or humidity, as this may affect its performance.
- Regularly check for any signs of wear or damage before use. If any parts are damaged, do not use the scale.
- Dispose of batteries responsibly, following local regulations for battery disposal.

Specific Safety Precautions for Use

- Do not overload the scale beyond its 100g capacity, as this may cause permanent damage.
- Handle the scale with care; dropping or bumping it may affect its accuracy.
- Keep the scale away from strong magnetic fields, as this can interfere with its operation.
- Avoid using the scale in the presence of strong vibrations, which may lead to inaccurate readings.
- If you notice any irregularities in scale readings, recalibrate the scale using the provided 100g calibration weight.

Instructions for Installation and Usage

1. Installation:

- Place the scale on a stable, flat surface away from direct sunlight and drafts.
- Insert two (2) AAA batteries into the battery compartment, ensuring correct polarity (+/-).
- Ensure the scale is turned off before inserting batteries.

2. Usage:

- Turn on the scale by pressing the power button.
- Allow the scale to warm up for a few seconds before use.
- Press the "Tare" button to reset the scale to zero before placing any items on it.
- Place the scale pan on the scale and wait for the reading to stabilize.
- Add your load gradually until you reach the desired weight, ensuring you do not exceed the 100g limit.
- After weighing, remove the pan and turn off the scale to preserve battery life.

Disposal Instructions

- Dispose of the MEC Reloading Scale Kit in accordance with local regulations.
- Do not dispose of the scale or its components in household waste.
- Ensure that batteries are removed and disposed of separately, following local battery disposal guidelines.

Contact Information for Further Support

For any safety inquiries or support regarding the MEC Reloading Scale Kit, please refer to the manufacturer's contact details provided with the product packaging.

Conclusion

By following these safety instructions, you can ensure the safe and effective use of your MEC Reloading Scale Kit. Always prioritize safety and consult the guide whenever you have questions about the product's operation. Thank you for your attention to these important safety measures.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk