

SINGLE STAGE PRESS STEEL SHOT CHARGE BAR - MEC RELOADING 1-1/4OZ #3-#6 SHOT SINGLE STAGE STEEL SHOT CHARGE BAR

[Reloading](#) > [Reloading Presses](#) > [Reloading Press Accessories](#)

This is a steel shot charge bar for single stage reloaders. Available to load from 7/8 oz. to 1-1/2 oz. of shot and #1 sizes down to #6.



Attributes

- Name: MEC RELOADING 1-1/4OZ #3-#6 SHOT SINGLE STAGE STEEL SHOT CHARGE BAR
- Manufacturer: MEC RELOADING
- Product no.: 749019394
- Mfr. No.: 30211436
- Size: 1-1/4 oz
- Delivery weight: 0.234kg
- Shipping height: 25mm
- Shipping width: 25mm
- Shipping length: 165mm
- UPC: 098489015516

Item details

Made in USA

Table of Contents

- Startpage
- Safety Instruction Guide for SINGLE STAGE PRESS STEEL SHOT CHARGE BAR
- About Us

Safety Instruction Guide for SINGLE STAGE PRESS STEEL SHOT CHARGE BAR

Introduction

Thank you for choosing the SINGLE STAGE PRESS STEEL SHOT CHARGE BAR by MEC RELOADING. This product is designed for use with single stage reloaders and allows you to load shot sizes ranging from #1 down to #6, with a capacity of 11/4 oz. This safety instruction guide provides essential information to ensure safe and effective use of the product, in compliance with the EU General Product Safety Regulation (GPSR).

General Safety Guidelines

- Always read and understand the instructions before using the product.
- Ensure that the product is used only for its intended purpose.
- Keep the product out of reach of children and vulnerable individuals.
- Regularly inspect the product for any signs of wear or damage.
- Report any unsafe products or accidents to the appropriate authorities.
- Stay informed about recall updates through the EU's Safety Gate platform.

Specific Safety Precautions for Use

- Do not exceed the recommended load capacity of 11/2 oz.
- Use only compatible shot sizes (#1 to #6) as specified.
- Always wear appropriate safety gear, including eye protection, when reloading.
- Ensure the work area is clean and free from distractions while using the product.
- Avoid using the product if you are tired or under the influence of drugs or alcohol.
- Follow all local laws and regulations regarding reloading and ammunition.

Instructions for Installation and Usage

1. Installation:

- Ensure your reloading press is on a stable and flat surface.
- Attach the steel shot charge bar securely to your single stage reloader according to the manufacturer's instructions.
- Verify that all connections are tight and that there are no loose parts.

2. Usage:

- Measure the desired amount of shot (between 7/8 oz. to 11/2 oz.) using the charge bar.
- Load the shot into the reloader, ensuring proper alignment and placement.
- Follow your reloader's instructions for completing the reloading process.
- After use, clean the charge bar to prevent buildup of residue and ensure longevity.

Disposal Instructions

- Dispose of the product in accordance with local regulations.
- Do not dispose of the product in regular household waste if it contains hazardous materials.
- Consider recycling options for metal components if applicable.

Contact Information for Further Support

For any safety inquiries or further assistance, please refer to the EUbased contact point provided by the manufacturer.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk