

STEEL SHOT CHARGE BAR - MEC RELOADING 10Z BB-#2 STEEL SHOT CHARGE BAR

[Reloading](#) > [Reloading Presses](#) > [Reloading Press Accessories](#)

This is a steel shot charge bar for single stage reloaders. Available to load from 7/8 oz. to 1-1/2 oz. of shot and BB sizes down to #3.



Attributes

- Name: [MEC RELOADING 10Z BB-#2 STEEL SHOT CHARGE BAR](#)
- Manufacturer: [MEC RELOADING](#)
- Product no.: 749019397
- Mfr. No.: 302100BB2
- Size: 1 oz
- Delivery weight: 0.236kg
- Shipping height: 25mm
- Shipping width: 25mm
- Shipping length: 165mm
- UPC: 098489012218

Item details

Made in USA

Table of Contents

- Startpage
- Safety Instruction Guide for STEEL SHOT CHARGE BAR MEC RELOADING 1OZ BB#2 STEEL SHOT CHARGE BAR
- About Us

Safety Instruction Guide for STEEL SHOT CHARGE BAR MEC RELOADING 1OZ BB#2 STEEL SHOT CHARGE BAR

Introduction

Thank you for choosing the STEEL SHOT CHARGE BAR MEC RELOADING 1OZ BB#2. This product is designed for use with single stage reloaders and allows you to load shot from 7/8 oz. to 11/2 oz. with BB sizes down to #3. This guide provides essential safety instructions to ensure safe and effective use of the product in compliance with the EU General Product Safety Regulation (GPSR).

General Safety Guidelines

- Always read and understand the instructions before using the product.
- Ensure that the product is used only for its intended purpose.
- Keep the product out of reach of children and vulnerable individuals.
- Regularly inspect the product for any signs of wear or damage before use.
- Follow all local laws and regulations related to reloading and ammunition.

Specific Safety Precautions for Use

- Use safety glasses and hearing protection when reloading.
- Avoid using the charge bar in wet or humid conditions to prevent rust and corrosion.
- Do not exceed the specified load limits (1 oz. maximum).
- Ensure that the charge bar is securely attached to the reloader before use.
- Do not attempt to modify the charge bar in any way.
- If you experience any issues during use, stop immediately and consult the product manual or seek professional assistance.

Instructions for Installation and Usage

1. Installation

- Ensure the reloader is powered off and unplugged.
- Attach the STEEL SHOT CHARGE BAR to the reloader according to the manufacturer's instructions.
- Confirm that the charge bar is locked in place and securely fastened.

2. Usage

- Set the desired load size on the charge bar (between 7/8 oz. and 11/2 oz.).
- Verify that the shot and BB sizes are appropriate for the charge bar (#3 or larger).
- Begin the reloading process by following the reloader's operational guidelines.
- Monitor the loading process to ensure that the charge bar is functioning correctly and safely.

Disposal Instructions

- Dispose of the product in accordance with local waste disposal regulations.
- Do not dispose of the product in household waste.
- Check for any recycling options available for metal parts.

Contact Information for Further Support

For any safety inquiries or additional support regarding the STEEL SHOT CHARGE BAR MEC RELOADING 1OZ BB#2, please refer to the manufacturer's contact information provided with your product.

Conclusion

By following the safety instructions outlined in this guide, you can ensure a safe and effective reloading experience with the STEEL SHOT CHARGE BAR MEC RELOADING 1OZ BB#2. Always prioritize safety and compliance with local regulations. Thank you for your attention to these important guidelines.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk