

STEEL SHOT CHARGE BAR - MEC RELOADING 1-1/8OZ BB-#3 STEEL SHOT CHARGE BAR

[Reloading](#) > [Reloading Presses](#) > [Reloading Press Accessories](#)

This is a steel shot charge bar for single stage reloaders. Available to load from 7/8 oz. to 1-1/2 oz. of shot and BB sizes down to #3.



Attributes

- Name: [MEC RELOADING 1-1/8OZ BB-#3 STEEL SHOT CHARGE BAR](#)
- Manufacturer: [MEC RELOADING](#)
- Product no.: 749019400
- Mfr. No.: 302118BB3
- Size: 1-1/8 oz
- Delivery weight: 0.236kg
- Shipping height: 25mm
- Shipping width: 25mm
- Shipping length: 165mm
- UPC: 098489012140

Item details

Made in USA

Table of Contents

- Startpage
- Safety Instruction Guide for STEEL SHOT CHARGE BAR MEC RELOADING 11/8OZ BB#3 STEEL SHOT CHARGE BAR
- About Us

Safety Instruction Guide for STEEL SHOT CHARGE BAR MEC RELOADING 11/8OZ BB#3 STEEL SHOT CHARGE BAR

Introduction

Thank you for choosing the STEEL SHOT CHARGE BAR MEC RELOADING 11/8OZ BB#3 STEEL SHOT CHARGE BAR. This product is designed for single stage reloaders and allows for loading shot from 7/8 oz. to 11/2 oz. with BB sizes down to #3. To ensure safe and effective use, please read this safety instruction guide carefully.

General Safety Guidelines

- Ensure that the product is used only for its intended purpose.
- Always follow the manufacturer's instructions for use and maintenance.
- Keep the product out of reach of children and vulnerable individuals.
- Inspect the product regularly for any signs of damage or wear.
- Report any unsafe products or accidents to the appropriate authorities.
- Stay informed about product recalls through the EU's Safety Gate platform.

Specific Safety Precautions for Use

- Always wear appropriate safety gear, including eye protection, when using the charge bar.
- Ensure that the charge bar is securely attached to the reloader before use.
- Do not exceed the maximum load capacity of the charge bar.
- Handle all components, including shot and powder, with care and follow safety guidelines for handling ammunition components.
- Store the charge bar in a cool, dry place when not in use to prevent damage.

Instructions for Installation and Usage

1. Installation:

- Ensure that your reloader is turned off and unplugged before installation.
- Locate the mounting area on your reloader where the charge bar will be attached.
- Align the charge bar with the mounting holes and secure it using the provided screws.
- Doublecheck that the charge bar is firmly attached and does not move.

2. Usage:

- Set the charge bar to the desired weight by adjusting the settings according to the manufacturer's instructions.
- Load the appropriate amount of shot into the charge bar.
- Operate the reloader according to the manufacturer's instructions, ensuring that the charge bar is functioning correctly.
- After use, clean the charge bar to remove any residue and maintain its functionality.

Disposal Instructions

- Dispose of the product in accordance with local regulations for electronic and mechanical waste.
- Do not dispose of the product in regular household waste.
- Consider recycling options for metal and plastic components where available.

Contact Information for Further Support

For any inquiries related to safety, usage, or maintenance, please refer to the manufacturer's contact information provided with your product packaging. It is important to have access to support for any questions or concerns regarding the safe use of the STEEL SHOT CHARGE BAR MEC RELOADING 11/8OZ BB#3 STEEL SHOT CHARGE BAR.

By following these guidelines, you can ensure a safe and effective experience with your reloading equipment. Thank you for prioritizing safety and compliance with the EU General Product Safety Regulation.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk