

DS-750 Digital Reloading Scale

[Reloading](#) > [Powder Handling](#) > [Powder Scales](#)

The Frankford Arsenal® DS-750 delivers extreme accuracy for precise measurement of powder, bullets, cases or loaded rounds. Simple controls allow for easy changes of units, tare weights or counting. Powder pan, carry bag and calibration weight included.

NO IMAGE
AVAILABLE

Attributes

- Name: [DS-750 Digital Reloading Scale](#)
- Manufacturer: [Frankford Arsenal](#)
- Product no.: EU1000317
- Mfr. No.: 205205
- Colour: Grey
- Delivery weight: 0.23kg
- Shipping height: 121mm
- Shipping width: 48mm
- Shipping length: 218mm
- UPC: 661120052050

Table of Contents

- Startpage
- Frankford Arsenal DS750 Digital Reloading Scale Safety Instructions
- About Us

Frankford Arsenal DS750 Digital Reloading Scale Safety Instructions

Introduction

Thank you for choosing the Frankford Arsenal® DS750 Digital Reloading Scale. This guide provides essential safety instructions to ensure safe and effective use of the scale. Please read this document carefully to understand how to operate the product safely and responsibly.

General Safety Guidelines

- Ensure the scale is used in a dry environment to prevent damage and ensure accurate readings.
- Keep the scale away from children and pets to avoid accidents.
- Do not exceed the maximum weight capacity of the scale to prevent damage.
- Regularly check the scale for any signs of wear or damage before use.
- Always use the scale on a stable, flat surface to ensure accurate measurements.
- In case of any malfunction, discontinue use immediately and consult customer support.

Specific Safety Precautions for Use

- Do not use the scale for measuring substances that are not intended for use with this product, such as liquids or hazardous materials.
- Avoid exposing the scale to extreme temperatures, humidity, or direct sunlight.
- Do not attempt to disassemble or repair the scale yourself. This may void the warranty and pose safety risks.
- Use only the provided calibration weight for adjustments to ensure accuracy.
- When using the tare function, ensure that the container is empty and properly placed on the scale before zeroing.
- Ensure that the power source is compatible with the scale to avoid electrical hazards.

Instructions for Installation and Usage

1. Unpacking the Scale

- Carefully remove the scale from the packaging.
- Ensure all components (scale, powder pan, carry bag, calibration weight) are included.

2. Setting Up the Scale

- Place the scale on a stable and flat surface.
- Ensure the scale is level for accurate measurements.
- Connect the power source if applicable.

3. Powering On the Scale

- Press the power button to turn on the scale.
- Allow the scale to warm up for a few moments before use.

4. Selecting Measurement Units

- Use the unit button to toggle between measurement units (grams, ounces, etc.) as needed.

5. Taring the Scale

- Place the empty powder pan on the scale.
- Press the tare button to zero the scale.

6. Measuring

- Add the desired amount of powder, bullets, or cases to the tared pan.
- Read the measurement displayed on the screen.

7. Calibration

- Use the provided calibration weight to ensure the scale is accurate.
- Follow the manufacturer's instructions for calibration procedures.

8. Turning Off the Scale

- Press the power button to turn off the scale after use.
- Store the scale in a safe, dry place.

Disposal Instructions

- Dispose of the scale in accordance with local regulations regarding electronic waste.
- Do not dispose of the scale in regular household waste.
- Remove batteries (if applicable) before disposal and dispose of them separately according to local guidelines.

Contact Information for Further Support

For any questions or concerns regarding the Frankford Arsenal® DS750 Digital Reloading Scale, please contact the manufacturer or refer to the product's official website for further assistance.

Conclusion

The Frankford Arsenal® DS750 Digital Reloading Scale is designed to provide precise measurements for your reloading needs. By following these safety instructions, you can ensure a safe and effective experience with your scale. Always prioritize safety and consult the guidelines provided for best practices. Thank you for choosing Frankford Arsenal.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk